

Re X4-A9.1

13 July 66

Comments

- ① The 0-80 key chart has seriously biased a lot of the thinking, in an undesirable direction ---
- ① Does not allow for a significantly larger NL key.
 - ② Puts the active surface of the shift in too close to core.
 - ③ Crowds in other function keys to central core.

② ASCII Pairings are incompatible with established typewriter practice. For the future this is a cost/conformity problem.

- ① Keys 6, 10-16, 35, 54-55 are affected. (Not including comma ~~and period~~ and period keys.)
- Eleven Keys